



Orientations:



Sliders



Feet

⚠ Warning!

Keep hands and fingers clear when closing.



Battery Adaptor Usage & Safety Information

This battery adaptor has been designed to allow the use of **MILWAUKEE® 18V M18™** and **DeWalt™ 18V XR** batteries with **Scanprobe Techniques Ltd X-Range pipeline inspection systems**.

Intended Use:

The adaptor enables these batteries to power the X-Range system in the same way they would power a compatible power tool. **Batteries must only be charged using their original manufacturer's approved charger.**

Environmental Protection:

- o The adaptor has been tested and rated **IP56** water ingress protection.
- o Recommended operating temperature: **-10°C to +40°C**.
- o Do not expose the adaptor or batteries to direct heat sources, prolonged sunlight, or submersion in water.

Battery Manufacturer Guidelines:

- o Always follow **the battery manufacturer's instructions** for charging, storage, and handling.
- o Store batteries in a **cool, dry location**, away from flammable materials.
- o Avoid leaving batteries fully discharged or fully charged for extended periods.
- o Inspect batteries regularly for signs of damage, swelling, or leakage.

Fire & Safety Precautions:

- o Lithium-ion batteries can pose a **fire risk if damaged or improperly handled**.
- o Charge and store batteries in an area with appropriate **fire suppression measures** (e.g., Class D fire extinguisher or fire blanket designed for lithium-ion fires).
- o Never attempt to use a battery that has been dropped, punctured, or exposed to excessive moisture.
- o In the event of overheating, unusual smells, or smoke, disconnect and isolate the battery safely.

General Considerations:

- o Only use genuine **MILWAUKEE®** or **DeWalt™** batteries that are **undamaged and in good condition**.
- o Do not attempt to modify, repair, or disassemble the adaptor.
- o Keep the adaptor and battery terminals **clean and free of debris**.
- o Ensure proper alignment and secure connection before use.

Part Numbers:

Battery Adaptor: 1020-1013-0
Cable Clips: 1020-2060-0

Support:

If you need any more support, you can contact our service department via email at service@scanprobe.com or call us on +44 203 253 2001. Scan the QR code for all our manuals, tutorials, and more from Scanprobe!



www.scanprobe.com



X-Range Battery Adapter

Compatible with all X-Range systems.




www.scanprobe.com




How to dock:


Hook on system



Lock unit in place



Unclip and open




Slide battery in until it clicks



Close lid to start charging



Secure the wire



Thank you for choosing Scanprobe for your pipeline inspection needs. To learn more, head to www.scanprobe.com